



FIRST INFORMATION REPORT

1459

First Information of a cognizable crime reported under section 154 Cr. P. C. at PS.

1. Dist Purulia Sub Divn. Shubola PS. Baghmundi Year 2018 FIR No. 109/18 Date 20.11.18
 2. i) Act I.P.C. Sections 379 ii) Act Section 109/18 Sections 109/18 Date 20.11.18
 iii) Act I.P.C. Sections 379 iv) Other acts & Sections X
 3. a) General Diary Reference : Entry No. X Time X
 b) Occurrence of Offence : Day 1069 Date 20.11.18 Time 20.05 hrs.
 c) Information received Date Sunday and Monday Time 18/11/18 and 19/11/18 B.G.D. No. 21:25 hrs to 20.42 hrs P.S.
 4. Type of Information : Written/Oral 20/11/18 Time 20.05 hrs. 1069
 5. Place of Occurrence : a) Direction and Distance from P.S. Typical
 b) Address At about 08 k.m. North East from P.S. to P.O. Seckhpard under P.PSP side, Baghmundi, Purulia.
 c) In case outside limit of this Police Station, then the name of P. S. Pinch No - 216 District No - 100
 6. Complainant / Informant :
 a) Name : Dukhabandhu Murmu
 b) Father's / Husband's Name Not noted
 c) Date / Year of birth Not noted d) Nationality Indian
 e) Address DE(CE)DPH PPSP Site, WSEDCI, Baghmundi Purulia.
 7. Details of known/suspected/unknown/accused with full particulars
 (Attach separate sheet, if necessary) : Unknown Mercant

8. Reasons for delay in reporting by the complainant/informant N/A
 9. Particulars of properties stolen/involved : (Attach separate sheet, if required) 142 Nos bare copper conductor
total length of copper conductor is approx 150 mtr.
 10. Total value of properties stolen/involved : Approx Rs - 162346.50/-
 11. Inquest report/U.D. Case no., if any : N/A
 12. FIR Contents : (Attach separate sheets, if required) N/A

The original typed complain which is treated as FIR is attached here with
and reproduced overleaf on 2nd and 3rd copy of FIR.

13. Action taken : Since the above report reveals commission of offence(s) u/s 379 I.P.C Officer-in-charge BAGHMUNDI P.S. DT. PURULIA
 registered the case and took up the investigation/directed SI Soumen Bera of jurisdiction. FIR read over to
 the Complainant/informant, admitted to be correctly recorded and a copy given to the Complainant/Informant free of cost.

Signature/Thumb impression of the Complainant/informant Dukhabandhu Murmu
 Signature of the Officer-in-Charge, Police Station with ANUP
 Name : SI OF POLICE
 Rank : o/c Bagmudi PS
 Number if any : OTPLORSUA

West Bengal State Electricity Distribution Company Limited

(A Govt. Of West Bengal Enterprise)

Purulia Pumped Storage Project

Bagmundi, Purulia-723152

WBSSEDCL

Ph:-(03252) 250201, Fax:- (03252) 250202, Email:-ppspsite@yahoo.com

Registered Office:- Bidyut Bhavan, Block-DJ, Sector-II, Bidhannagar, Kolkata 700 091

CIN:-U40109WB2007SGC113473, Website:- www.wbsedcl.in

Memo no.PPSP/OPH/Switchyard/FIR/1169

Date: 20.11.2018

To

The Officer –in-Charge

Bagmundi Police Station

Bagmundi

Purulia

Sub: - FIR against theft of bare copper conductor from the earthing point of bus and gantry structure at 400KV Switchyard under PPSP Site Bagmundi Purulia

Dear Sir,

There are Four (04) Nos. Feeder emanating from 400KV Switchyard PPSP Site named as 400KV PPSP-Durgapur-I, 400KV PPSP-Durgapur-II, 400KV PPSP-New PPSP-I, 400KV PPSP-New PPSP-II. All feeders are sent through bus duct support structure and Gantry tower. All structure are earthing by 100 sq.mm, 19 strand bare copper conductor connected with underground earth mesh for safety purpose for both human as well as the equipment.


It is reported from 400KV Switchyard that some theft has occurred in 400KV bay area. On inspection of the site on 400KV Switchyard, It is found that 142 nos. bare copper conductor used for earthing of bus duct support structure and gantry tower have been cut off from the structure base by the miscreant. As a result safety of the equipment and human has been totally loss due to forced isolation from the earth mesh. It is observed from the CCTV footage that the miscreant continued the cutting and stilling activity between 21:28hr on 18/11/2018 to 00:40hr on 19/11/2018. Total theft copper conductor length is approximately 150mtr. The cost of theft copper conductor will be approximately RS.162346.50.

You are request to visit the Place of occurrence and give clearance for urgent restoration of earthing of bus duct support structure and gantry so that protection system may be restored within shortest possible time.

You are requested to treat this information as FIR and booked the miscreant under the law of land.

Thanking you

Yours faithfully



(Dukhabandhu Murmu)


D.E (E), OPH

PPSP Site, WBSSEDCL

Bagmundi, Purulia

Mobile No: 8170043823

Received on-20/11/18 at P.S 20.05 hrs.
started Baghmundi P.S case no- 108/18
date-20/11/18 u/s 379 I.P.C



Officer-in-charge
BAGHMUNDI P.S

DT.-PURULIA