



FIRST INFORMATION REPORT

1. First Information of a cognizable offence reported under section 154 Cr. P. C. at PS
 Purulia Sub-Divn. Raghunathpur P.S. Santaldih Year 2021 FIR No. 64/21 Date 02/09/21
 The Electricity Act, 2003 Section 136(1)(a) ii) Act Sections
 iii) Act Sections iv) Other acts & Sections

3. a) General Diary Reference : Entry No. 78 Time 16:15 hr
 b) Occurrence of Offence : Day In between 23/08/21 and 24/08/21 Date Time
 c) Information received Date 02/09/21 Time 16:15 hr G.D. No. 78 at the P.S.

4. Type of Information : Written / Oral written
 5. Place of Occurrence : a) Direction and Distance from P.S. 05 km east from the P.S.
 b) Address STPS - Purgapur transmission line, near Uka village, P.S. Santaldih, Dist - Purulia Beat No. J.L. no - 21, Anchal - Toradih.
 c) In case outside limit of this Police Station, then the name of P.S. District

6. Complainant / Informant :
 a) Name Ar. Mah. Baidy, Asst. Eng. (E) & Incharge, Purulia Line P.B. (E & M) Subdivision
 b) Father's / Husband's Name Sr. Harindranath Baidy under Purulia Area office, WBSE TEL
 c) Date / Year of birth 15/04/1993 d) Nationality Indian
 e) Address Present add - Raghunathpur P.S. KV Sub station, Bakuria more, Cheliyama road, Raghunathpur Purulia

7. Details of known/suspected /unknown/accused with full particulars
 (Attach separate sheet, if necessary) :

Unknown miscreants

8. Reasons for delay in reporting by the complainant/informant X

9. Particulars of properties stolen/involved : (Attach separate sheet, if required) : Total 47 pieces of angle, Total weight - 7.14 kg. (approx)

10. Total value of properties stolen/involved 34,284/- (Rupees Thirty four Thousand, Two Hundred Eighty four only)

11. Inquest report/U.D. Case No., if any X

12. FIR Contents : (Attach separate sheet, if required)

The original written complaint of the complainant which has been treated as FIR is attached herewith.

Tapan Tewari
 02/09/21


13. Action taken : Since the above report reveals commission of offence(s) u/s 136(1)(a) of The Electricity Act, 2003

registered the case and took up the investigation/directed SI. Biswajit Maiti, IC BCW, P.S. Santaldih to take up the investigation/transferred to P.S. Santaldih on point of jurisdiction. FIR read over to the Complainant/informant, admitted to be correctly recorded and a copy given to the Complainant/informant free of cost.

is an original written complaint
 Tapan Tewari
 02/09/21

Signature / Thumb impression of the Complainant/informant

Tapan Tewari
 02/09/21
 Signature of the Officer-in-Charge Police Station with Name TAPAN TEWARI Dist - Purulia
 Rank S.I. of Police, Santaldih P.S.
 Number if any Dist - Purulia



West Bengal State Electricity Transmission Company Limited

(A Government of West Bengal Enterprise)

Office of the Assistant Engineer

Purulia Line Transmission (O&M) Sub-Division

Administrative Building (Near Purulia 132 kV Substation Campus)
Bongabari, P.O. – Vivekananda Nagar, Dist. - Purulia, PIN – 723147

Phone No.: 03252-246065, Mob. No.: 9434910214

Email Id.: purulialinetoffice@gmail.com

WBSETCL

Memo No.: AE/PRL/Tr.(O&M)/SD/E-10/063

Dated: 24.08.2021

To
The Officer-In-Charge,
Santaldih Police Station,
Santaldih, Purulia

Sub: Request for lodging FIR against the theft of GI Angles of different sizes from tower of 220 kV STPS – Durgapur d/c transmission line, under the jurisdiction of Purulia Line Tr. (O&M) Sub-Division, WBSETCL.

Dear Sir,

Relevant details regarding the theft of the materials are given below:

1. Date of occurrence: In between 23.07.2021 and 24.08.2021
2. Date of detection: 24.08.2021 (10:00 hrs to 12:00 hrs)
3. Detected by: Maintenance gang headed by Shri Adhir Chandra Mahato, Hg.Sr.L.M., Shri Basudeb Ganguly, Hr.Gr.T.S.H.
4. Place of occurrence: near Uka village
5. Description of stolen materials: GI Angles of sizes 50 × 50 × 6 mm and 65 × 65 × 6 mm with nuts and bolts of the T/L nos. 20 and 21 of 220 kV STPS – Durgapur d/c transmission line
6. Quantity of stolen materials:

| Sl. No. | Tower Location No. | No. of angle pieces stolen | Approximate length (m) | Approximate weight (kg) |
|---------|--------------------|----------------------------|------------------------|-------------------------|
| 1. | 20 | 23 | 60 | 336 |
| 2. | 21 | 24 | 67 | 378 |

7. Value of stolen property: Approximately Rs. 34,284.00 (Rupees Thirty Four Thousand Two Hundred Eighty Four only)
8. Whether overhead line was charged or not: The overhead line was charged at 220 kV.
9. Date of last checking: 23.07.2021
10. Cause of delay: NA

Under the above circumstances, you are requested to lodge an FIR in this regard and supply the copy of the same to the undersigned at the earliest.

Thank you.

Yours faithfully,

(Signature)
(ARNAB BAUG) Sr. In-Charge
Purulia Line Tr. (O&M) Sub-Division
Vivekananda Nagar, V. Nagar
P.O. - Bongabari, Dist. - Purulia, PIN - 723147 (W.B.)

DESIGNATION: ASSISTANT ENGINEER (E & T) IN-CHARGE
PURULIA LINE TRANSMISSION (O&M) SUB-DIVISION,
UNDER PURULIA AREA OFFICE, WBSETCL

FATHER'S NAME: HARENDRA NATH BAUG

DATE OF BIRTH: 15.04.1993

NATIONALITY: INDIAN

PRESENT ADDRESS: RAGHUNATHPUR 132 kV SUBSTATION,
EKUNJA MORE, CHELIYAMA ROAD,
RAGHUNATHPUR, PURULIA

Received on 02/09/21 at
16:15 hrs and started Santaldih P.S
Case no. 64/21 dtd. 02/09/21
U/S-136(C)(a) of The Electricity
Act, 2003.

Tapan Kumar
SI
Santaldih P.S
02/09/21
Inspector-in-Charge
Santaldih P.S.
Dist.-Purulia