

FIRST INFORMATION REPORT

First Information of a cognizable crime reported under section 154 Cr. P. C. at PS

1. Dist. 309 Purulia Sub-Divn. Raghunathpur P.S. Raghunathpur Year. 2022 FIR No. 53/22 Date 06/05/22
2. i) Act. x Sections. x ii) Act. x Sections. x
 iii) Act. x Sections. x iv) Other acts & Sections. 136 of Electricity Act 2003 & Amendment Act 2007.
3. a) General Diary Reference : Entry No. 276 Time. 16:45 hrs.
 b) Occurrence of Offence : Day. last night on 05/05/22 Time. at night hours
 c) Information received Date. 06/05/22 Time. 16:45 hrs. G.D. No. 276 at the P.S.
4. Type of Information : Written / Oral Written (Type)
5. Place of Occurrence : a) Direction and Distance from P.S. 02.5 Km. West
 b) Address. At - Raghunathpur 132/33/11 KV Sub station under Purulia area office, WBSE - P.C.L., on Chelama Road, P. Raghunathpur Dist. Purulia Beat No. 3L No - 115 AL No. VII
 c) In case outside limit of this Police Station, then the name of P.S. x District. x
6. Complainant / Informant :
 a) Name. Ashok Kumar Samal, S.E. In Area Manager, Purulia Area office, WBSE
 b) Father's / Husband's Name. x
 c) Date / Year of birth. x d) Nationality. Indian
 e) Address. At - Near Basirbandh on Chelama Road, P.S. Raghunathpur, Dist. Purulia.
7. Details of known/suspected /unknown/accused with full particulars
 (Attach separate sheet, if necessary) :

① Unknown Miscreants.

8. Reasons for delay in reporting by the complainant/informant. x
9. Particulars of properties stolen/involved : (Attach separate sheet, if required) : Stolen away 24 M of 33 KV Copper Male Contact Rod of 3 phase Transfer Bus isolated of e nos.
10. Total value of properties stolen/involved. x
11. Inquest report/U.D. Case No., if any : x
12. FIR Contents : (Attach separate sheet, if required)

The original written Complaint of the Complainant which has been located as FIR, is attached herewith

13. Action taken : Since the above report reveals commission of offence(s) u/s. 136 of Electricity (Amendment) Act-2007 Inspector-in-charge Raghunathpur Dist. Purulia (W.B.)

registered the case and took up the investigation/directed. PSI. Mendam Sabab to take up the investigation/transferred to P.S. x on point of jurisdiction. FIR read over to the Complainant/informant, admitted to be correctly recorded and a copy given to the Complainant/informant free of cost.

Signature / Thumb impression of the Complainant/informant Ashok Kumar Samal 06/05/22

Inspector-in-charge Raghunathpur P. S. Dist.-Purulia (W.B.)

Inspector-in-charge Raghunathpur Police Station with Name Mukul Kumar Rank SI of Raghunathpur PS. Number if any. x



WEST BENGAL STATE ELECTRICITY TRANSMISSION CO. LTD.

(A West Bengal Government Enterprise)

Office of the Superintending Engineer & Area manager,
Purulia Area office

Administrative Building (Near Purulia 132kV Sub-Station campus),

At Bongabari, P.O. – V.Nagar, Dist. – Purulia, Pin:- 723147

E-mail: puruliaareaoffice@gmail.com ,Mob: 9434910060

Memo No.: WBSETCL/PAO/FIR/101

Dated:06.05.2022

To
The Officer-In-Charge,
Raghunathpur Police Station,
Purulia, W.B.

Sub: Lodging FIR against theft of materials inside the premises of Raghunathpur 132/33/11 kV Substation, under Purulia Area Office, Dist- Purulia, WBSETCL.

Sir,

I, Shri Ashok Kumar Samal, S/o Late Bishnu Mohan Samal, Superintending Engineer & Area Manager, Purulia Area Office, Dist- Purulia, WBSETCL being empowered under section(s) of Electricity Act-2003 & Electricity (Amendment) Act-2007 lodging complaint against theft of material inside the premises of Raghunathpur 132/33/11 kV Substation, under Purulia Area Office, Dist- Purulia, WBSETCL. As Shri Abhishek Saha, S/o Ashim Saha A.E. & In Charge of Raghunathpur 132/33/11 kV Substation is out of station for some official works today.

That in the late night on 05.05.2022, 24 nos of 33 KV Copper Male contact Rod of 3 Phase Transfer Bus-Isolators of 8 nos. 33 KV Bays inside the premises of Raghunathpur 132/33/11 KV Substation have been stolen by some unknown miscreants which was informed by the A.E. & In Charge of the said substation over telephone to the undersigned at 07:30 A.M. on 06.05.2022. The matter was inspected by me physically and found the materials stolen by the unknown miscreants after entering into the substation premises by cutting the intertwined barbed wire at the south west corner of the existing boundary wall of the substation. Out of this 8 nos. 33 KV bays, 3 nos. were transformer bays & 5 nos. were feeder bays. Thus the WBSETCL has sustained a loss as well as privilege of providing power at the time of emergency due to such theft.

Therefore, you are requested to treat this complaint as F.I.R. u/s 136 of Electricity Act-2003 & Electricity (Amendment) Act-2007 for taking further course of action in this regard.

As such, your earliest permission for repair & maintenance work is solicited to provide uninterrupted power supply in the interest of public service.

Thanking You

Yours faithfully,

(ASHOK KUMAR SAMAL)

S.E. & Area Manager,
Purulia Area Office,
Purulia,
W.B.S.E.T.C.L.

Received on 06/05/22 at 16:45 hrs and
Started Raghunathpur PS Case NO-
53/22 dt- 06/05/22 u/s 136 of Electricity
Act 2003 & Amnt Act 2007.

[Signature]
06/5/22
Inspector-in-charge
Raghunathpur P. S.
Dist.-Purulia (W.B.)