



FIRST INFORMATION REPORT

1877

First information of a cognizable crime reported under section 154 Cr. P.C. at P.S.

1. Date: Purulia Sub-Divn: Raghunathpur P.S. Santalalih Year: 2023 FIR No. 77/23 Date: 03/11/2023

2. (a) Act: Electricity Act Sections: 136(i)(a) (b) Act: _____ Sections: _____

(c) Act: _____ Sections: _____ (d) Other acts & Sections: _____

3. (a) General Diary Reference: Entry No. 131 Time: 20:05 hrs

(b) Occurrence of Offence: Day: Thursday Date: 02/11/2023 Time: not noted

(c) Information received Date: 03/11/2023 Time: 20:05 hrs G.D. No. 131 at the P.S.

4. Type of Information: Written

5. Place of Occurrence: (a) Direction and Distance from P.S. approx 1 km, west side from P.S. to P.O

(b) Address: SMB NO. 55 and SMB NO. 73 to their respective Solar banks from Santalih 10 MW Solar Power Plant (Zone - A, Part Area of S.T.P.S Township Post No. Anehal - Deali, J.L.N.O. 65

(c) In case outside limit of this Police Station, then the name of P.S. _____ District _____

6. Complainant / Informant: (a) Name: Anup Kumar Mandi

(b) Father's / Husband's Name: Jaladhath Mandi

(c) Date / Year of birth: not noted (d) Nationality: Indian

(e) Address: Superintending Engineer (E), Solar, Purulia Regional Office, WBSEDL

7. Details of known accessories/unknown/accused with full particulars (Attach separate sheet, if necessary):

unknown miscreants

8. Reasons for delay in reporting by the complainant/informant: _____

9. Particulars of properties stolen/involved: (Attach separate sheet, if required): 6 sq. mm. DC Copper Solar Cable approximately 1890 meter.

10. Total value of properties stolen/involved: RS- 1,50,000.00

11. Inquest report/U.D. Causes, if any: _____

12. FIR Contents: (Attach separate sheets, if required)

The Original written complaint of the complainant which is treated as F.I.R. is attached herewith.

13. Action taken: Since the above report reveals commission of offence(s) 136(i)(a) Electricity Act

registered the case and took up the investigation directed ASI- Rabinhanath Basak to take up the investigation/transferred to P.S. _____ on point of jurisdiction. FIR read over to the Complainant/informant, admitted to be correctly recorded and a copy given to the Complainant/informant free of cost.

Anup K. Mandi
3.11.23
Signature/Thumb impression of the Complainant/informant

03/11/23
Inspector-in-Charge
Santalalih P.S.
Dt. Purulia

Binoy Krishna Paul
Signature of the Officer-in-Charge, Police Station with
Name: BINOY KRISHNA PAUL
Rank: SI of Santalih Police Station
Number if any: Purulia
at 03/11/2023



West Bengal State Electricity Distribution Company Ltd.

(A Govt. of West Bengal Enterprise)

OFFICE OF THE REGIONAL MANAGER, PURULIA REGIONAL OFFICE

E-mail- rm.purulia@wbsedcl.in

Telephone no.: (03252) 223671, Fax- (03252) 223671

Memo no:- RM/PRO/SOLAR/4016

Dated:- 03.11.2023

To,
The Inspector -in- Charge
Santaldih P.S.
Dist. - Purulia

Sub:- Report for theft of 6 Sq mm DC Copper Cable from Santaldih 10MW Solar PV Power Plant (Zone - A, Part - A area) within the premises of Santaldih Power Plant Township Under Purulia Regional Office.

Sir,

After getting a written complaint from Arup Kr. Goswami, Prop. Of the agency M/S Goswami Electrical & Construction engaged for the work of Operation & Maintenance of the Santaldih Solar Power Plant and for providing security personnel at Plant, regarding theft occurred at Santaldih Solar Power Plant at midnight of 01.11.2023 and 02.11.2023. From the statement of the agency, it revealed that theft and damaged occurred by cut of approximately 1890 meter 6 Sq mm DC Copper Solar Cable by miscreants from the SMB No.- 55 and SMB No.-73 to their respective solar panels from our Santaldih 10 MW Solar Power Plant (Zone - A, Part - A area) situated within the premises of Santaldih Power Plant Township.

I, Sri Anup Kr. Mandi, Superintending Engineer (E), W.B.S.E.D.C.L inspected the site jointly on 02.11.2023 with Arup Kr. Goswami, Prop. Of the agency M/S Goswami Electrical & Construction and the security personnel and technical staffs engaged there. On site inspection, theft and damage of 6 sq.mm. DC Copper Solar Cable found from the SMB No.- 55 and SMB No.- 73 and the total length of the said cable is approximately 1890 meter costing at present market value is approx. Rs. 1,50,000.00 and the total cost for the repairing the same will come Rs.2,10,000.00.

At that area, on 01.11.2023 at the evening shift (from 2 PM to 10 PM), Dinesh Gorain and Tapan Mahato were guarding the area and in the night shift (from 10 PM to 6 AM dated. 02.11.2023), Binay Pandey, Dhiraj Ansary & Habulal Rajak were guarding the area. On dated 02.11.2023, Tapan Mahato identified the theft during guarding the area in morning shift (from 6 AM to 2 PM).

The theft area already visited by your Police Personnel with us at the evening on 02.11.2023 and found one nos Hacksaw Frame with Blade which is already submitted at your Police Station.

So, I request you to please treat this as a information of theft at Santaldih 10MW Solar PV Power Plant (Zone - A, Part - A area).

This is a formal intimation and may be treated as F.I.R.

*Received on 03/11/2023 at 20:05 hrs
and started Santaldih P.S case no. 77/23
dt 03/11/2023, U/S-136(i) (a) Electricity Act.*

*Binay Krishna Paul
S.I. of Santaldih P.S.
Purulia
dt 03/11/2023
Inspector-in-Charge
Santaldih P.S.
Dt.-Purulia*

Mob no.:- 8900799421 (Official)
8101178328 (Personal)

Yours Faithfully,

Anup
3.11.23

(A.K.MANDI)
Superintending Engineer (E)
Purulia Regional Office
WBSEDCL

Superintending Engineer (E), Solar
Purulia Regional Office
W.B.S.E.D.C.L

Registered office of the Company- Bidyut Bhavan, Block- DJ, Sector- II,
Bidhannagar, Kolkata- 700091.

Corporate Identity Number (CIN) - U40109WB2007SGC113473.

Website of the Company: www.wbsedcl.in,